

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

U-14

History of original corner establishment:

None, corner established this survey.

DIAGRAM

T5S R37E

SW1/16 S 27

PLS 1206

1987

Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

At the corner point: set $2\frac{1}{2}$ " x 30" aluminum pipe 24" into the ground with 36" dia. stone mound around it. $2\frac{1}{2}$ " dia. aluminum cap mkd. as shown in the corner diagram.

From the corner point: (Bearing trees)

A 9" dia. White Fir bears S 36 W at 20.0 ft. dist. mkd. SW1/16 S27 BT

A 18" dia. Western Larch Bears N 20 W at 21.7 ft. mkd. SW1/16 S27 BT

Attached U.S.F.S. 54-9 and 54-3 signs to the bearing trees, and painted the face of the blaze and a 6" band around the bearing trees red. Attached a $\frac{3}{4}$ " dia. brass I.D. washer, mkd. PLS 1206, between the B and T scribes. Set a steel fence post 4' North with U.S.F.S. 54-9 sign attached. Used $18\frac{1}{2}$ declination on a staff compass for readings to the bearing trees, and used a steel tape to measure to a nail set in the side of the trees at the base.

This corner was monumented to U.S.F.S. specifications on October 26, 1987, witnessed by Tom Fisk, Larry McBroom and Andy Marlette.

**UNION COUNTY
SURVEYOR**

Date Received 5-1-89

Filed 5-15-89

By G. LANGLITZ, DEPUTY

File No. 88-89 R

Office of... County Surveyor..... County of... Union

State of... Oregon

I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

by

(DEPUTY)

Form R6-7100-57 (9/71)

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
SEPTEMBER 21, 1977
JAMES D. HANLEY
1206