USDA-FOREST SERVICE GPO 9.	40-117			
File No. 4-5	CORNER RECORD (Ref. FSM 7	(SEARCH)	Tract or Survey No	Cor. No. 5 C
153 R. 375		_ County	Survey No.	140
Marid. Coll	_ N.F W - W	State _ O	Κ'.	
CORNER DIAGRAM	DESCRIBE CORNER MONUME			
1				
1 - X	1			
N T				2
	DESCRIBE BEARING TREES OF	OTHER OFFICIA	AL ACCESSORIES FOUND	
1 200	DOWN ROTTEN			
ı	DOWN ROTTEN	15" 20	570W 76	Service SIN CALIF
	DONN ROTTON			11 11 11
PHOTO IDENTIFICATION DATA	1	•		
Photo No.	PLACED LOCATIO	NO PASTE	R ON TRUIT	190 EAST
Filed At.	-	,		10 =11,
Object Ident	DESCRIBE CORNER LOCATION	RELATIVE TO N	EAR-BY FEATURES, ALSO	HOW TO REACH CORNER
Signature				`
LANE COORDINATE POSITION DATA	4			
StateZone			•	
Х	-			
Υ	1			
Estab, By				
Agency	a			

UNION COUNTY SURVEYOR
Date Received
Date Filed 12-23-87
By G. LANGCITZ, DEPUTY
File No. 364-87R

## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

William R. Gradon conducted the survey of Township 5 South, Range 37 East, W.M., under GLO contract No. 445 dated June 1, 1882.
Gradon set a post for the corner point,

from which:

A black pine 22" dia. bears N 22 E at 26 lks. A black pine 16" dia. bears S 75 E at 60 lks. A black pine 15" dia. bears S 40 W at 46 lks.

A black pine 18" dia. bears N 55 W at 8 lks.

V-5 DIAGRAM T5S R37E S 30 | S 29 S 31 | S 32 PLS 1206 1987

## Description of corner evidence found:

A 6' long, down and rotted Lodgepole Pine, size indeterminable, bears N 22 E at 26 lks. mkd. 9 BT.

A 3' long, down and rotted Lodgepole Pine, size indeterminable,

bears S 40 W at 46 lks. mkd. with visible but not legible scribing.

A 6' long, down and rotted Lodgepole Pine, size indeterminable,
bears N 55 W at 8 lks. mkd. T5S R37E S30 BT.

## Description of monument and accessories I established to perpetuate the

original location of this corner: At the corner point as re-established from the remains of the three original found bearing trees: set  $2\frac{1}{2}$ " x 30" aluminum pine 24" into the ground, with 36" dia. stone mound around it.  $2\frac{1}{2}$ " aluminum cap is mkd. as shown in the corner diagram.

From the corner point: (New BT's)

A 8" dia. Lodgepole Pine bears S 69 W at 22.3 ft. dist. mkd. T5S R37E S31 BT A 9" dia. Lodgepole Pine bears S 78 E at 41.7 ft. dist. mkd. T5S R37E S32 BT A 14" dia. Spruce bears N 48 E at 16.9 ft. dist. mkd. T5S R37E S29 BT A 14" dia. Spruce bears N 19 W at 34.2 ft. dist. mkd. T5S R37E S30 BT

Atached U.S.F.S. 54-9 and 54-3 signs to the bearing trees, and painted the face of the blaze and a 6" band around the bearing trees red. Attached a 3/4" dia. brass I.D. washer between the B and T scribes. Set a steel fence post 4' North of the monument with U.S.F.S. 54-9 sign attached to it. Used  $18\frac{1}{2}$  declination on a staff compass for readings to the bearing trees, and used a steel tape to measure to a nail set in the side of the bearing trees, at the base.

This corner was monumented to U.S.F.S. specifications on August 24, 1987, witnessed by Tom Fisk, Larry McBroom, Tim Rouse and Andy Marlette.

	UNION COUNTY SURVEYOR
	Date Received 5-1-89
Office of County Surveyor County of Union State of Oregon I became continuous	Data Filed 5-15-89
The strument was filed in the	Proced STINGUIS DON'TY
for record on the day of, 19	File No. 90-89 R
(COUNTY OFFICIAL) (DEPUTY)	

Form R6-7100-57 (9/71)

REGISTERED **PROFESSIONAL** LAND SURVEYOR

> Nobeli JAMES D. HANLEY

₩ GPO-798-274