CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

William R. Gradon conducted the survey of Township 5 South, Range 37 East, W.M., under contract No. 445 dated June 1, 1882.

Gradon set a post for the corner point, from which:

A Fir 24" dia. bears N 35 E at 20 lks. dist. A Fir 24" dia. bears S 10 W at 40 lks. dist.

V - 19DIAGRAM T5S R37E 1 S 26 ⁴ S 35 PLS 1206 1987

Description of corner evidence found:

A 24" dia. x 20' long downed snag bears S. 10° W. at 26.4 ft. dist., mkd. $\frac{1}{4}$ S BT.

Description of monument and accessories I established to perpetuate the

original location of this corner: Corner point re-established from the one original found bearing tree.

At the corner point, set a $2\frac{1}{2}$ " x 30" aluminum pipe with a $2\frac{1}{2}$ " aluminum cap, 18" into the ground, with a 36" stone mound. Cap is marked as shown in the corner diagram.

From the corner point: (New BT's)
A 16" dia. Douglas Fir bears N. 3° E. at 40.6 ft. dist., mkd. ½ S 26 BT.
A 24" dia. Douglas Fir bears S. 29° E. at 17.5 ft. dist., mkd. ½ S 35 BT.

Set a steel fence post 4. East from the monument and attached a USFS 54-9 sign. Painted the face of the blaze and a 6" band around the bearing trees red. Attached I.D. washer and USFS 54-9 and 54-3 signs to the bearing trees. Used $18\frac{1}{2}^{\circ}$ declination on a staff compass for readings to the bearing trees. Used a steel tape to measure to a nail set in the side of the trees. The 3/4" brass I.D. washer was nailed be tween the B and T scribes.

This corner was monumented to USFS specifications on August 13, 1987, witnessed by Larry McBroom and Tim Rouse.

Union County Surveyor
Data Received 5-1-89
Dato Filed 5-15-89
BY G. LANGLITZ DEPUTY
File No. 94 - 89 R

Office of County Surveyor County of Union	By G. LANGLITZ DEPUT File No. 94 - 89 R
State of. Oregon	office

Form R6-7100-57 (9/71)

(COUNTY OFFICIAL) REGISTERED PROFESSIONAL LAND SURVEYOR

..... by

OREGON C JAMES D. HANLEY

☆ GPO--798-276