CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

William R. Gradon conducted the survey of Township 5 South, Range 37 East, W.M., August 14 to August 25, 1882, under GLO Contract No. 445.

Gradon set a post for the corner point, from which: A Black Pine, 14" dia., bears S. 65° E. at 62 lks. dist.

A Black Pine, 14" dia., bears N. 700 W. at 40 lks. dist.

X-5 T5S R37E 31 S 32 PLS 1206 1987

Description of corner evidence found:

No evidence found.

Description of monument and accessories I established to perpetuate the

original location of this corner: After a thorough search of the area revealed no corner evidence.

At the proportioned point; set a $2\frac{1}{2}$ " x 30" aluminum pipe with a $2\frac{1}{2}$ " aluminum cap 28" into the ground. Constructed small stone mound around the monument. Cap is marked as shown in the corner

From the corner point: (New BT's) A 12" dia. Spruce bears S. 11° W. at 42.0 ft. dist., mkd. $\frac{1}{4}$ S 31 BT. A 15" dia. Spruce bears N. 52° E. at 30.1 ft. dist., mkd. $\frac{1}{4}$ S 32 BT.

Set a steel fence post 4 ft. North from the monument and attached a USFS 54-9 sign. Painted the face of the blaze and a 6" band around the bearing trees red. Attached I.D. washer and USFS 54-9 and 54-3 signs to the bearing trees. Used 1820 declination on a staff compass for readings to the bearing trees. Used a steel tape to measure to a nail set in the side of the trees. The 3/4" dia. I.D. washer mkd. PLS 1206 was nailed between the B and T scribes.

This corner was monumented to USFS specifications on September 15, 1987, witnessed by Tom Fisk and Andy Marlette.

UNION COUNTY SURVEYOR Data Raceived 5-1-89 Office of County Surveyor County of Union State of Oregon, I hereby certify that the within instrument was filed in this office for record on the...... day of....... , 19.....

COUNTY OFFICIAL REGISTERED PROFESSIONAL Form R6-7100-57 (9/71) LAND SURVEYOR

> ames & Hand OREGON JAMES D. HANLEY 1206

..... by

(DEPUTY)

☆ GPO-788-276