CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Jacob C. Cooper conducted the survey of the First Standard Parallel Lines of Township 5 South, Ranges 34, 35, 36 and 37 East, W.M., under GLO contract No. 397 dated July 1, 1881.

Cooper set a post for the corner point,

from which:

A Spruce 16" dia. bears N 50 E at 28 lks. A Spruce 10" dia. bears N 47 W at 26 lks.

Z-7DIAGRAM C T5S R37E 🛓 S32 PLS 1206 1987

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the

original location of this corner: After a thorough search of the area revealed no

original corner evidence: At the proportioned point, set a $2\frac{1}{2}$ " x 30" aluminum pipe with a $2\frac{1}{2}$ " aluminum cap, 24" into the ground, with no stone mound. Cap is marked as shown in the corner diagram.

From the corner point: (New BT's) A 12" dia. Spruce bears N. 26° W. at 18.6 ft. dist., mkd. $\frac{1}{4}$ S 32 SC BT. A 9" dia. Spruce bears N. 60° E. at 7.0 ft. dist., mkd. $\frac{1}{4}$ S 32 SC BT.

Set a steel fence post 4° South from the monument and attached a USFS 54-9 sign. Painted the face of the blaze and a 6° band around the bearing trees red. Attached I.D. washer and USFS 54-9 and 54-3 signs to the bearing trees. Used $18\frac{1}{2}$ ° declination on a staff compass for readings to the bearing trees. Used a steel tape to measure to a nail set in the side of the trees. The 3/4° dia. I.D. washer mkd. PLS 1206 was nailed between the B and T scribes.

This corner was monumented to USFS specifications on September 15,

1987, witnessed by Larry McBroom and Tim Rouse.

UNION COUNTY SURVEYOR Date Received 5-1-89 Date Filed

Office of County Surveyor	County of Union	
	rtify that the within instrument was filed in this office	
for record on the day of		
***************************************	by	
(COUNTY OFFICIAL)	(DEPUTY)	

Form R6-7100-57 (9/71)

REGISTERED PROFESSIONAL LAND SURVEYOR

☆ aPO---798-276

OREGON JAMES D. HANLEY 1206