

T. 5 S., R. 37 E., Willamette Meridian, Oregon

CHARGE

The following field notes describe the remonumentation of certain original corner points, township 5 south, range 37 east, Willamette Meridian, Oregon, as provided for in the Special Instructions, Group Number 1000, Oregon, dated July 13, 1979, "Investigation of Physical Evidence of Corner Positions and Accessories, Followed by Remonumentation of Corner Points, with New Accessories when Needed."

The remonumentation of original corner points was made at the request of the United States Forest Service, in conjunction with their Land Line Location Program.

The mean magnetic declination is 20° E.

(Remonumenting a corner established by Jacob C. Cooper, U. S. Deputy Surveyor, in 1881)

The standard $\frac{1}{4}$ sec. cor. of sec. 34 only, on the S. bdy. of the Tp., determined at record bearing and distance from the remains of the original bearing trees:

A decayed and burned pine stump, size indeterminate, bears N. 20° E., 17 lbs. dist., no marks visible.

A larch, 39 ins. diam., bears N. 85° W., 16 lbs. dist., with scribe marks SC & S visible on open boughs.

At the corner point

Set an aluminum post, 28 ins. long, $2\frac{1}{4}$ ins. diam., 23 ins. in the ground, with aluminum cap mkd.

SC
T 5 S R 37 E
 $\frac{1}{4}$ S 34
1982

from which a new bearing tree

A fir, 19 ins. diam., bears N. 51° E., 40 lbs. dist., mkd. $\frac{1}{4}$ S 34 SC BT.

Set a steel fence post alongside aluminum post.

NOTE: MICROFICHE CARD AVAILABLE IN COUNTY SURVEYOR'S RECORDS.

UNION COUNTY SURVEYOR

Date Received 9-26-83

Date Filed 11-18-83

By G. LANGLITZ, DEPUTY

File No. 409-83 R