History of original comer establishment:

Corner not established in original survey.

	A-2
DIAGRAM	
W 1/16	R38E S 31
. T5s	R38E

No record of subsequent remonumentation found in County records. Description of corner evidence found:

None

See map of survey dated June 1980.


Description of monument and accessories I established to perpetuate the original location of this corner:

At proportionate distance I set $2^{1}2^{1} \times 30^{11}$ iron pipe with brass cap marked as shown, 28^{11} in ground, from which:

A 7" tamarack bears N5QW, 3.4 feet marked W 1/16 S31 BT

A 8" spruce bears S7W, 19.5 feet marked W 1/16 S6 BT

Raised mound of stone





Brass washer nailed to 8.T.blaze
Used steel tape and magnetic compass
with 18 East declination.
Measured to center of all 8.T.s

Office of	reasured to center of all B.T.s		
State of	t the within instrument was filed in this offic UNION COUNTY		
(COUNTY OFFICIAL)	(DEPUTY) Date Received	-	
Form R6-7100-57 (9/71)	Date Filed		
	. Ву		
	F'e No. 684-84 R		