## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1863 by Timothy W.Davenport under General Land Office Contract No. 102. Surveyor General Record states:

Set post for corner from which;

A spruce 8 in. dia. bears N2OE, 8 links

A spruce 8 in. dia. bear's \$15E, 10 links

A-3	
DIAGRAM	
T4S R38E	
1 <sub>4</sub> S 31	
\$ 6	- 1
T58 R38E	1
	- 1

Retraced in 1881 by W.B.Barr under General Land Office Contract No.388. No record of subsequent remonumentation was found in County records. Description of corner evidence found:

None

See map of survey dated June 1980.

Description of monument and accessories I established to perpetuate the original location of this corner:

At proportionate distance I set  $2^{1}2^{1} \times 30^{11}$  iron pipe with brass cap marked as shown, 14" in ground, from which:

A 7" lodgepole pine bears N49E, 20.7 feet marked 4 S31 BT

A 7" lodgepole pine bears \$45E, 12.8 feet marked  $\frac{1}{4}$  \$.6 B T

Raised mound of stone.

T4S R38E

14 S31
 S6

T5S, R38E
 1980
 OPLS 644

PROFESSIONAL LAND SURVEYOR

OREGON V JULY 10, 1841 DUANE I. GRIFFITH 544

Brass washer nailed to B.T.blaze. Used stgel tape and magnetic compass with 18 East declination. Measured to center of all B.T.s

State of		
(COUNTY OFFICIAL)	(DEPUTY)	
orm R6-71CO-57 (9/71)	Date Filed & spo-700.	276
	Ву	•