


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established under GLO Contract No. 102 by Timothy W. Davenport, dated July 20, 1868. Surveyor General field record states: Set qr. sec. post, made mound of rock

T 5 S R 38 E A-23



DESCRIPTION OF CORNER EVIDENCE FOUND:

Found a 4 ft. diam. x 1 1/2 ft pile of stone in East/West running fence line approx. 20 ft. West of ancient fence corner to North/East/West fence corner. No mounds of stone exist in the area from old fence rock jacks.

SEE SURVEY 046-2021

DESCRIPTION OF MONUMENT AND ACCESSORIES I

ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At center of found mound of stone, I set a 2 1/2" x 30" aluminum pipe, 16" in the ground, with 3" aluminum cap, marked as shown below, in a mound of stone 4 ft. diam. from which:

NEW BEARING OBJECTS:

- A 6" Douglas Fir bears North 49° East, a dist. of 38.50 ft., marked 1/4 S36 BT.
- A Rock Outcrop, 3' x 1' x 1/2' exposed bears South 28° East, a dist. of 31.30 ft., marked X BO.
- A 12" White Fir bears South 66° West, a dist. of 61.20 ft., marked 1/4 S1 BT.
- A 6" Douglas Fir bears North 10° West, a dist. of 37.20 ft., marked 1/4 S36 BT.


Falls in East/West fence line.

I hereby certify that the corner was perpetuated on September 29, 2021.
Witness: Kyle A. Tucker

REGISTERED PROFESSIONAL LAND SURVEYOR
OREGON June 2, 2010 JEFFREY S. HSU 83571

Renewal Date: June 30, 2023

UNION COUNTY SURVEYOR
Date Received <u>11/1/21</u>
Date Filed <u>11/1/21</u>
Filed By <u>Ally G. Mumford DEPUTY</u>
File Number <u>047-2021R</u> 047



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination. Distances are to a 60d spike driven into the right side of the root crown of the bearing trees. Bearings are to a brass washer marked OPLS 83571 in the Bt blaze of the new bearing trees. Distance and bearing of the stone is to the center of the chiseled X.