CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T5S R38EC-18

S 2

DESCRIPTION OF CORNER EVIDENCE FOUND:

A fence post with a BLM approx. corner tag bears South 84° West, a distance of 23.10 from new monument

SEE SURVEY 035-2020

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey I set a 5/8" x 30" iron pin, 28" in the ground, with 2 1/2" aluminum

cap marked as shown below and in a mound of stone 2' diam..

From which:

NEW BEARING OBJECTS:

A 6" Engelmann Spruce bears South 6° East a dist. of

5.45 ft., marked CW1/16 S2 BT. A 7" White Fir bears North 52° West a dist. of 1.70 ft., marked CW1/16 S2 BT.

Set steel fence post approx. 1 ft. South.

I hereby certify that the corner was monumented on September 9, 2020.

Witness: Kyle A. Tucker

GRIFFITH BAGELY T5S R38E W 1/16 S2 2020 **OPLS 83571**

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON JEFFREY S. HSU 83571

Renewal Date: June 30, 2021

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

UNION COUNTY SURVEYOR Date Received 10/12/2020