
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T5S R38ED-17



GRIFFITH

T5S R38E

S 1/16

DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY 035-2020

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey I set a 5/8" x 30" iron pin, 28" in the ground, with 2 1/2" aluminum cap marked as shown below and in a mound of stone 2'

diam.,

From which:

NEW BEARING OBJECTS:

An 18" White Fir bears South 51° East a dist. of 21.65 ft., marked S1/16 S2 BT.

A 17" Douglas Fir bears South 41° West a dist. of 20.70 ft., marked S1/16 S3 BT.

Set steel fence post approx. 1 ft. East.

I hereby certify that the corner was monumented on September 10, 2020.

Witness: Kyle A. Tucker

2020 **OPLS 83571** I used a steel tape and magnetic compass in the

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON JEFFREY S. HSU 83571

Renewal Date: June 30, 2021

establishment of the new accessories. I used 14 $^{\circ}\,$ East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

UNION COUNTY SURVEYOR Date Received 10/12/2020 Date Filed 10/12/2020 File Number 0652020R