


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 5 S R 38 E D-18



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY 035-2020

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey I set a 5/8" x 30" iron pin, 34" in the ground (4" below the road surface), with 2 1/2" aluminum cap marked as shown below,

From which:

NEW BEARING OBJECTS:

A 4" Western Larch bears North 63° East a dist. of 11.85 ft., marked SW 1/16 S2 BT.


A 9" Western Larch bears South 77° West a dist. of 26.25 ft., marked SW 1/16 S2 BT.

Set steel fence posts approx. West a dist. of 27.7 ft. West and North 2° East a dist. of 13.00 ft.

Monument falls approx. 5' West of Eastern edge of Northwest/Southeast bearing forest road

I hereby certify that the corner was monumented on September 9, 2020.

Witness: Kyle A. Tucker



Renewal Date: June 30, 2021

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

