### CERTIFIED RECORD OF LAND CORNER MONUMENTATION

# HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

# T5S R38EE-14 S 10

#### DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY 035-2020

# DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey I set a 5/8" x 30" iron pin, 27" in the ground, with 2 1/2" aluminum cap marked as shown below and in a 2' diam. mound of

stone,

From which:

# **NEW BEARING OBJECTS:**

A 13" Ponderosa Pine bears South 7° West a dist. of

49.00 ft., marked W 1/16 S10 BT. A 16" Ponderosa Pine bears North 26° West a dist. of 13.95 ft., marked W 1/16 S3 BT.

Set steel fence post approx. 1 ft. East.

I hereby certify that the corner was monumented on  $% \left\{ 1\right\} =\left\{ 1\right\}$ October 10, 2020.

Witness: Kyle A. Tucker

GRIFFITH BAGATY T5S R38E **S**3 W 1/16 **S10 OPLS 83571** 2020

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON 2. 2010 JEFFREY S. HSU

83571 Renewal Date: June 30, 2021

I used a steel tape and magnetic compass in the establishment of the new accessories. I used  $14^{\circ}$ East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

**UNION COUNTY SURVEYOR** Date Received 10/12/2020 Date Filed 10/12/2020 File Number <u>065 2020</u> R