## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

### HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 5 S R 38 E E-22

S 12

#### DESCRIPTION OF CORNER EVIDENCE FOUND:

None found.

SEE SURVEY 046-2021

# DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position by Survey I set a 5/8" x 30" iron pin, 21" in the ground, with 2 1/2" aluminum cap marked as shown below, in collar of stone 3' diam., from which:

#### NEW BEARING OBJECTS:

A 9" Ponderosa Pine bears South 5° West, a dist. of 81.75 ft., marked W 1/16 S12 BT A 15" Ponderosa Pine bears North 19° West, a dist. of 68.90 ft., marked W 1/16 S1 BT

Set steel fence post approx. 2 ft. South

I hereby certify that the corner was monumented on October 1, 2021.

Witnesses: Kyle Tucker, Emmitt Ambert

REGISTERED
PROFESSIONAL
LAND SUPVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2023

S1 W 1/16 S12

2021

OPLS 83571

UNION COUNTY
SURVEYOR

Date Received 11 121

Filed By 11 G. Which Court

File Number 050 2021

I used a steel tape and magnetic compass in the establishment of the new accessories. I used  $14^\circ$  East declination. Distances are to a 60d spike driven into the right side of the root crown of the bearing trees. Bearings are to a brass washer marked OPLS 83571 in the Bt blaze of the new bearing trees.