


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 5 S R 38 E F-19



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY 035-2020

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:


At position by survey I set a 5/8" x 30" iron pin, 28" in the ground, with 2 1/2" aluminum cap marked as shown below and in a 2' diam. mound of stone,
From which:

NEW BEARING OBJECTS:

A 7" White Fir bears South 13° East a dist. of 5.60 ft., marked CN 1/16 S11 BT.
A 9" Douglas Fir bears North 88° West a dist. of 16.95 ft., marked CN 1/16 S11 BT.

Set steel fence post approx. 1 ft. West.

I hereby certify that the corner was monumented on September 10, 2020.
Witness: Kyle A. Tucker



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2021

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

**UNION COUNTY
SURVEYOR**

Date Received 10/12/2020

Date Filed 10/12/2020

Filed By [Signature] DEPUTY

File Number 071-2020R