

J-7

R623

Form 9600-9  
(December 1979)  
(Formerly 9100-9)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

ORIGINAL

23

FIELD NOTES  
OF THE

REMONUMENTATION OF CERTAIN ORIGINAL CORNER POINTS,

TOWNSHIP 5 SOUTH, RANGE 38 EAST,

[Lined area for field notes]

Of the WILLAMETTE Meridian,  
in the State of OREGON

EXECUTED BY

Scott R. McIntyre, Cadastral Surveyor

Under special instructions dated July 13, 19 79, approved July 17, 1979

which provided for the surveys included under U.S. Survey/Group  
Number 1000, and assignment instructions dated July 30, 19 82

Survey commenced August 20, 19 82  
Survey completed August 31, 19 82

<b>UNION COUNTY SURVEYOR</b>	
Date Received	<u>2-2-84</u>
Date Filed	<u>2-28-84</u>
By	<u>G. LANGLITZ, DEPUTY</u>
File No.	<u>832-84 R</u>

40

**Remonumentation of Certain Original Corner Points,  
T. 3 S., R. 38 E., Willamette Meridian, Oregon**

Set a file, 12 ins. long, 6 ins. below surface of dirt road, 15 lks. wide, bears E. and W.

From which a reference monument

An aluminum post, 28 ins. long, 2 1/4 ins. diam., set 12 ins. in the ground, to solid rock, in a mound of stone, 4 ft. base, to top, for a reference monument, bears North, 38 lks. dist., with aluminum cap mkd. T58 R38E 1/4 S17 25 FT TO COR NW 1882 and an arrow pointing to the corner.

Set a steel fence post alongside aluminum post.

The cor. of secs. 7, 8, 17, and 18, determined at record bearing and distance from the remains of the original bearing trees:

A decayed pine stump, size indeterminate, bears N. 86° E., 13 lks. dist., no marks visible.

A pine snag, 10 ins. diam., bears S. 63° E., 8 lks. dist., with scribe marks S17 BT visible on open blaze.

A larch, 15 ins. diam., bears S. 63° W., 20 lks. dist., with healed blaze.

A pine snag, 10 ins. diam., bears N. 34° W., 52 lks. dist., with scribe marks S7 BT visible on open blaze.

At the corner point

Set an aluminum post, 28 ins. long, 2 1/4 ins. diam., 23 ins. in the ground, with aluminum cap mkd.

T 5 S R 38 E  
S 7 | S 8  
S 18 | S 17  
1982

from which new bearing trees

A spruce, 29 ins. diam., bears N. 22° E., 56 lks. dist., mkd. T58 R38E S8 BT.

A fir, 10 ins. diam., bears S. 70° E., 44 lks. dist., mkd. T58 R38E S17 BT.

A spruce, 6 ins. diam., bears N. 53° W., 25 1/4 lks. dist., mkd. T58 R38E S7 BT.

Set a steel fence post alongside aluminum post.

Corner is located 45 lks. N. of dry creek bed, course E.

The 1/4 sec. cor. of secs. 8 and 17, determined at the center of a root hole, with the remains of the original corner tree alongside, a fir, 14 ins. diam., with scribe mark S visible on opened blaze, from which the remains of the original bearing trees:

A spruce, 28 ins. diam., bears S. 49° W., 20 lks. dist., with healed blaze.

**UNION COUNTY  
SURVEYOR**

Date Received 2-2-84

Date Filed 2-28-84

By G. LANGLITZ DEPUTY

File No. 832-84R

Remonumentation of Certain Original Corner Points,  
T. 5 S., R. 38 E., Willamette Meridian, Oregon

CHAINS

A fir snag, 11 ins. diam., bears N. 60° W., 2 lks. dist., with illegible scribe marks visible on opened blaze.

At the corner point

Set an aluminum post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, in a collar of stone, with aluminum cap mkd.

T 5 S R 38 E  
¼  $\frac{S 8}{S 17}$   
1982

from which a new bearing tree

A fir, 18 ins. diam., bears N. 30° W., 39 lks. dist., mkd. ¼ S8 BT.

Corner is located 45 lks. N. of creek, 5 lks. wide, course E.

The ¼ sec. cor. of secs. 6 and 7, determined at record bearing and distance from the remains of the original bearing trees:

A root hole, bears S. 70° E., 15 lks. dist.

A root hole, bears N. 20° W., 20 lks. dist., with a down and decayed larch alongside, 7 ins. diam., with scribe marks S T visible on partially healed blaze.

At the corner point

Set an aluminum post, 28 ins. long, 2½ ins. diam., 23 ins. in the ground, with aluminum cap mkd.

T 5 S R 38 E  
¼  $\frac{S 6}{S 7}$   
1982

from which new bearing trees

A fir, 15 ins. diam., bears S. 13° W., 36 lks. dist., mkd. ¼ S7 BT.

A spruce, 20 ins. diam., bears N. 8° W., 48 lks. dist., mkd. ¼ S6 BT.

Set a steel fence post alongside aluminum post.

UNION COUNTY  
SURVEYOR

Date Received 2-2-84

Date Filed 2-28-84

By G. LANGLITZ DEPUTY

File No. 832-84R

PAGE 3/3