CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by W. B. Barr under GLO contract number 388 dated May 7, 1881. Surveyor General field notes state:

Set stake 4 ft long 4 in diam 18 in ground for 1/4 sec. corner, from which:

Black Pine 12 in diam bears S 20° E 18 lks dist

Black Pine 12 in diam bears N 65° W 21 lks dist

S 11

T5S R38EJ-19

DESCRIPTION OF CORNER EVIDENCE FOUND:

None. Area has been logged extensively.

SEE SURVEY 035-2020

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At proportionate position I set a 2 1/2" x 30" aluminum pipe, 29" in the ground with 3" aluminum cap marked as shown below and in a 2' diam.

collar of stone,

from which:

NEW BEARING OBJECTS:

A 16" White Fir bears North 6° East a dist. of 27.90 $\,$ ft., marked 1/4 S11 BT. BLM Boundary tags on tree face South and East.

A 5" White Fir bears South 72° East a dist. of 4.00

ft., marked 1/4 S14 BT. A 10" Western Larch bears South 54° West a dist. of

22.45 ft., marked 1/4 S14 BT. A 12" Lodgepole Pine bears North 66° West a dist. of 37.75 ft., marked 1/4 S11 BT. Tree was formerly used as a barbed wire fence corner.

Set steel fence post approx. 1 ft. West

New East/West bearing fence line falls approx. 16 ft. North.

I hereby certify that the corner was monumented on October 19, 2020. Witness: Kyle A. Tucker

REGISTERED PROFESSIONAL SURVEYOR

OREGON JEFFREY S. HSU 83571

Renewal Date: June 30, 2021

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

UNION COUNTY **SURVEYOR**

