
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

N/A

Description of monument and accessories I established to perpetuate original location of this corner:

At the position determined by survey, I set a standard USFS 2½ ins. diam. by 30 ins. long alum. pipe, 22 ins. in the ground, with clear DEEP-1 magnet at base and 4 ft. diam. stone mound to top, with 3¼ ins. diam. alum. cap, mkd as shown:

From which:

A Douglas fir, 14 ins. diam., bears S. 83° E., 141.2 ft. dist., mkd. N1/16 S15 BT. A white fir, 14 ins. diam., bears S. 70° W., 67.1 ft. dist., mkd. N1/16 S16 BT.

Set guard posts ± 5 ft. S'ly with Property Boundary (54-2) sign and ± 7 ft. N'ly with Property Boundary (54-2) and Land Survey Monument (54-9) signs attached.

All new bearing trees are marked on a single blaze and have a nail with a brass washer stamped "LS 2648" right side center for distance measurements.

Painted 6 ins. red bands and added Bearing Tree (54-3) and Land Survey Monument (54-9) signs as needed to all bearing trees.

Auto C/A geographic position: Lat. 45°07'59.9" N Long. 118°03'21.0" W

I hereby certify that the corner was monumented and accessories taken as described, using a Warren Knight staff compass, set with 15° East declination, and steel tape on August 13, 2014.

Witnesses: Kristina Powell, Brenda Johnson and Justin Seal



REGISTERED PROFESSIONAL LAND SURVEYOR

Deceased

OREGON
JANUARY 18, 1994
RON C. WALTER
2648

Renewal Date: June 30, 2016

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
July 22, 1977
WILLIAM R. WELLS

1106 Renewal Date: June 30, 2016

UNION COUNTY
SURVEYOR

Date Received 2 25/5

Date Filed 2 25/5

By L. G. Line
File No. 027-2015 R

<u>NOTE:</u> See "Explanation for Successor Certifying Surveyor" statement in Narrative of Record of Survey , CS 010-2015, filed concurrently with this Land Corner Record.