


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 5 S R 38 E K-15



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 029-2026

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by Survey I set a 5/8" x 30" iron pin, 28" in the ground and in a 1.5 ft. diam. collar of stone, with 2 1/2" aluminum cap marked as shown below, from which:


NEW BEARING OBJECTS:

A 7" Western Larch bears South 67° East, a distance of 12.20 feet, marked CN 1/16 S15 BT.
A 5" White Fir bears South 9° West, a distance of 1.05 feet, marked CN 1/16 S15 BT.

Set steel fence post approx. 1 ft. West

I hereby certify that the corner was monumented on June 24, 2026

Witness: Kyle Tucker



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2027

I used a tape and compass in the establishment of the bearing trees. 14° East was used for declination and measured to a brass washer marked "OPLS 83571" and tacked to the opened BT blaze. Distance was to a 60-D spike in the root crown on the right side of the tree.

UNION COUNTY
SURVEYOR

Date Received

7/13/26

Date Filed

7/13/26

Filed By

File Number

024-2026R