
History of original corner establishment:

None



Description of corner evidence found:

N/A

Description of monument and accessories I established to perpetuate original location of this corner:

At the position determined by survey, I set a standard USFS 2% ins. diam. by 30 ins. long alum. post, 26 ins. in the ground, with 3% ins. diam. alum. cap, and rock collar, with clear DEEP-1 magnet at base, mkd as shown:

From which:

A ponderosa pine, 15 ins. diam., bears N. 40½° E., 56.5 ft. dist., mkd. S1/16 S15 BT. A white fir, 15 ins. diam., bears S. 42½° E., 63.3 ft. dist., mkd. S1/16 S15 BT.

Set guard posts ±5 ft. S'ly with Property Boundary (54-2) sign and ±5 ft. N'ly with Property Boundary (54-2) and Land Survey Monument (54-9) signs attached.

Note: No healthy trees of reasonable size to West.

All new bearing trees are marked on a single blaze and have a nail with a brass washer stamped "LS 2648" right side center for distance measurements.

Painted 6 ins. red bands and added Bearing Tree (54-3) and Land Survey Monument (54-9) signs as needed to all bearing trees.

Auto C/A geographic position: Lat. 45°07'32.6" N Long. 118°03'18.2" W

I hereby certify that the corner was monumented and accessories taken as described, using a Warren Knight staff compass, set with 15° East declination, and steel tape on August 13, 2014.

Witnesses: Kristina Powell, Brenda Johnson and Justin Seal



REGISTERED PROFESSIONAL LAND SURVEYOR

Deceased

OREGON
JANUARY 18, 1994
RON C. WALTER
2648

Renewal Date: June 30, 2016

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
July 22, 1977
WILLIAM R. WELLS
1106

Renewal Date: June 30, 2016

UNION COUNTY SURVEYOR
Date Received 2 25 5
Date Filed 2 25/15
By NG Glim
File No. 029-WISR

 $\underline{\textbf{NOTE:}} \ \, \textbf{See "Explanation for Successor Certifying Surveyor" statement in Narrative of Record of Survey , CS 010-2015, filed concurrently with this Land Corner Record.}$