


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 5 S R 38 E M-18



DESCRIPTION OF CORNER EVIDENCE FOUND:

No original evidence found.
Found BLM approx. corner loc. tag which bears approx. 50 ft North westerly of surveyed position.

SEE SURVEY NUMBER 029-2026

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by Survey I set a 5/8" x 30" iron pin, 28" in the ground and in a 2 ft. diam. collar of stone, with 2 1/2" aluminum cap marked as shown below, from which:


NEW BEARING OBJECTS:

A 9" White Fir bears South 74° West, a distance of 32.20 feet, marked SW 1/16 S14 BT.
A 9" White Fir bears North 1° West, a distance of 21.85 feet, marked SW 1/16 S14 BT.


Set steel fence post approx. 0.5 ft. West

I hereby certify that the corner was monumented on June 11, 2026

Witness: Kyle Tucker, Emily McClelland



REGISTERED
PROFESSIONAL
LAND SURVEYOR


OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2027

I used a tape and compass in the establishment of the bearing trees. 14° East was used for declination and measured to a brass washer marked "OPLS 83571" and tacked to the opened BT blaze. Distance was to a 60-D spike in the root crown on the right side of the tree.

UNION COUNTY
SURVEYOR

Date Received 7/13/26

Date Filed 7/13/26

Filed By 

File Number 029-2026R