CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishmen	nt:	DIAGRAM
Corner not established by or	riginal survey.	T5S R38E
		CN 1/16 Sec. 27
Description of corner evidence found:		
None		
Description of monument and accesso	ries I established to perpetuate the	
original location of this corner:		
At the corner position determined aluminum pipe, 18 india. at base to top of cap,	rmined by survey and subdivision of ches in the ground and supported in with aluminum cap, marked:	a mound of stone, 3 ft. T5S R38E
From which we mark new bearing trees: An 8" Douglas Fir, scribed "CN 1/16 S27 BT" on a double blaze, bears N 60°W 24.7 feet.		C N 1/16†S27
		C PLS 1099
A 16" Douglas Fir, scribe blaze, bears N 17°E 5.0	d "CN 1/16 S27 BT" on a double	1984
•		.
Magnetic Compass (20° East	d "LS 1099" to lower blaze of new Bl Declination)	
Steel Tape		UNION COUNTY
October 9, 1984 REGISTERED	Witnesses:	SURVEYOR
PROFESSIONAL LAND SURVEYOR	Gary Langlitz Ray Crapo Doug Wright	Date Received 11-13-84
		Date Filed 11-13-84
Jack A. A. Mart		
GARY L. LANGLITZ 1699		By <u>G. LANGLITZ, DEPUT</u> File No. <u>1020 - 84 R</u>
	County of	
State of /	hereby certify that the within instrument was filed in	this office

Form R6-7100-57 (9/71)

for record on the...... day of......, 19.....

(COUNTY OFFICIAL) (DEPUTY)