


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not established during the original GLO survey. No record exists in the Union County records.

S-17



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner point determined by survey at a point on line and midway between the East 1/4 and N.E. corner of Section 27, we set a 2"x22" aluminum pipe, 20" in the ground, with aluminum cap, marked:

From which we mark new bearing trees:

A 12" Douglas Fir, scribed "N 1/16 S 27 BT" on a double blaze, bears N 22°W 3.9 ft.,

And a 14" Douglas Fir, scribed "N 1/16 S 26 BT" on a double blaze bears N 74°E 44.5 ft.

T5S R38E
N 1/16
S27 † S26
PLS 1099
1984


Attached brass washer marked "LS 1099" to lower blaze of new BT's.

Magnetic Compass (20° East Declination)
Steel Tape

October 9, 1984

Witnesses:

Gary Langlitz, LS 1099
Ray Crapo
Doug Wright



UNION COUNTY SURVEYOR
Date Received <u>11-13-84</u>
Date Filed <u>11-13-84</u>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>1023-84 R</u>

Office of..... County of.....
State of..... I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

(DEPUTY)