## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

T. Davenport surveyed the 1st Standard Parallel South under contract No. 102 dated July 20, 1863.

Record states:

Set post corner to Secs 33&34 from which A Red Fir 20 inch in dia. bears N 70° W 25 lks. dist.

A Pine 24 inch " " N 22° E 136 lks. dist.

A Pine 36 inch " " S 20° W 40 1ks. dist.

| Z-13       |         |    |    |     |   |
|------------|---------|----|----|-----|---|
| DIAGRAM    |         |    |    |     |   |
| SC         |         |    |    |     |   |
| . <b>T</b> | 5       | S  | R  | 38  | E |
|            | G       | 33 |    |     |   |
|            | <u></u> | 33 | S  | 34  | _ |
|            | PI      | S  | 12 | 206 |   |
| 1991       |         |    |    |     |   |
|            |         |    |    |     |   |

W. Barr retraced the 1st Standard Parallel South under contract No. 388 dated May 7, 1881.

Record states: Corner destroyed trees standing and agreeing with description. Reestablished by post 4 ft long 4 in diam. 18 in ground. Description of corner evidence found:

Found 3' dia. Fir stump bears N.  $70^{\circ}$  W., 16.5 feet dist. marked with axe chop marks.

Found 3' dia. Ponderosa Pine stump bears S. 20° W., 26.4 feet dist. marked with "B" high on stump. Found stump hole which bears N. 22° E., 87.8 feet dist.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner point as reestablished from the found bearing tree remains, set 1½" x 30" galv. iron pipe 24" into the ground, constructed 36" dia, stone mound around the monument. 2½" brass cap is marked as shown in the corner diagram.

From which, new bearing trees:

A 13" dia. Ponderosa Pine bears N. 32° E., 22.0 feet dist. marked T5S R38E S34 SC BT on double blaze.

A 16" dia. Ponderosa Pine bears S. 13° E., 12.3 feet dist. marked T5S R38E S34 SC BT on double blaze.

A 14" dia. Ponderosa Pine bears S. 52° W., 15.7 feet dist. marked T5S R38E S33 SC BT on double blaze.

A 6" dia. Ponderosa Pine bears N. 71½° W., 10.0 feet dist. marked T5S R38E S33 SC BT on double blaze.

Set steel fence post 2' west from the corner monument. Attached USFS 54-9 sign to the fence post. Also attached 54-9 and 54-3 signs to the new bearing trees and 54-3 signs to the original bearing trees.

I certify that the above corner was properly monumented under my direct supervision on August 28, 1991, as witnessed by Larry McBroom and David Smith.

File No

Office of County Surveyor County of Union

State of Oregon I hereby certify that the within instrument was filed in this office
for regord on the Land September 23, 1977

OREGON
SEPTEMBER 23, 1977

JAMES D. HANLEY

1206

6.7100. 57 (9/71)

Form R6-7100-57 (9/71)

Data Received 9/13/9/

REGISTERSO