


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This Section Corner was set by deputy Surveyor Timothy W. Davenport, under Contract No. 102, dated July 20, 1863. He states he set a post for the corner to sec's 34 & 35. Made mound of rock.



Description of corner evidence found:

At the assumed section corner location I found a mound of stone with a 1/2 in. iron pin in the center. The mound of stone was along side an ancient fence corner rock jack. Also at a point which bears N 81 20 W, 44.28 feet from the above mentioned mound of stone, I found a stone 18" x 12" x 7" buried in the ground approximately 8" and setting upright. There is no evidence of markings and no record of this stone. It appears to have been placed in position more recently than the mound of stone as there is no moss present on the stone.

Description of monument and accessories established to perpetuate the original location of this corner:

With no other evidence existing and the corner position appears correct by survey, I accepted the mound of stone as the true section corner. I then set an Alum. Cap on a 2" x 30" pipe, with a magnet fixed in the cap at the corner location. I buried the pipe to within 18" above the surface of the ground. I then placed a large mound of stone 3 1/2 feet dia. and 2 feet high covering the monument. There are no bearing trees available in the vicinity of the corner.

UNION COUNTY SURVEYOR	
Date Received	<u>9-22-87</u>
Date Filed	<u>11-2-87</u>
By	<u>G. LANGLITZ, DEPUTY</u>
File No.	<u>148-87R</u>

REGISTERED PROFESSIONAL LAND SURVEYOR	
<i>James H. Hambleton</i>	
<u>9-25-87</u>	
OREGON JULY 10, 1964 JAMES H. HAMBLETON 645	

REFER TO SURVEY 28-87

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL) (DEPUTY)