


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This $\frac{1}{4}$ corner was set by deputy surveyor Timothy W. Davenport under Contract No. 102, dated July 20, 1863. He states he set quarter sec. post in a mound of rock.



Description of corner evidence found:

At the assumed $\frac{1}{4}$ corner location, I found a mound of earth and stone along side an ancient rock jack and fitting the GLO call of being 10.50 chains west of a dry branch. No other evidence was available at the corner location.

Description of monument and accessories established to perpetuate the original location of this corner:

With no other evidence available and the corner position appears correct by survey, I accepted the mound of stone as the true $\frac{1}{4}$ corner. I then set an Alum. Cap on a 2" x 30" pipe, with a magnet in the cap, at the corner location. I buried the pipe to within 18" above the surface of the ground. I then placed a large mound of stone 4 feet dia. and 2 feet high covering the monument. There are no bearing trees available in the vicinity of this corner.

UNION COUNTY SURVEYOR
Date Received <u>9-22-87</u>
Date Filed <u>9-25-87</u>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>137-87 R</u>

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>James H. Hambleton</i>
<u>9-25-87</u>
OREGON JULY 10, 1964 JAMES H. HAMBLETON 645

REFER TO SURVEY 28-87

Office of..... County of.....
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL) (DEPUTY)