CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This Section Corner was set by deputy surveyor Timothy W. Davenport, under Contract No. 102, dated July 20, 1863. He states he set a post for the corner to Sec's. 35 & 36. Made mound of rock.



Description of corner evidence found:

At the assumed section corner location I found a mound of stone grown over by sage brush and being N 45 00 W, 6 feet from an ancient rock jack. This mound of stone fits a GLO call of being South of a bluff a distance of 5 chains. No other evidence is available at the corner location.

Description of monument and accessories I established to perpetuate the original location of this corner:

With no other evidence available and the corner position appears correct by survey, I accepted the mound of stone as the true section corner. I then set an Alum. Cap on a 2" x 30" pipe, with magnet fixed in the cap, at the corner location. I buried the pipe to within 15" above the surface of the ground. I then placed a large mound of stone 4 feet dia., 2 feet high covering the monument. There are no bearing trees available in the vicinity of this corner.

Date Received 9-22-87	LAND SURVEYOR
	Vanies & Vin blue
Date Filed 9-25-87	9-25-87 DREGON
BY G. LANGUITZ DEPUTY	JAMES H. HAMBLETON 645
File No. 1/2 - 87 R	

Office of	County of
	tify that the within instrument was filed in this office
for record on the day of	, 19
· · · · · · · · · · · · · · · · · · · ·	by
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

☆ GPO---798-276