


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This $\frac{1}{4}$ corner was set by deputy surveyor Timothy W. Davenport, under Contract No. 102, dated July 20, 1863. He states he set a quarter section post in a mound of rock.



Description of corner evidence found:

At the assumed $\frac{1}{4}$ corner location I found a mound of earth and stone grown over with grass and sage brush and being along an existing fence line. I also found traces of an ancient Indian trail 5.0 chains to west as is mentioned in the GLO topographic calls that Mr. Davenport made during his survey. No other evidence was available at the corner location.

Description of monument and accessories I established to perpetuate the original location of this corner:

With no other evidence available and the corner position appears correct by survey, I accepted the mound of stone as the true $\frac{1}{4}$ corner. I then set an Alum. Cap on a 2" x 30" pipe, with a magnet fixed in the cap, at the corner location. I buried the pipe to within 20" above the surface of the ground as area is very rocky. I then placed a large mound of stone 4 feet dia. and 2 $\frac{1}{2}$ feet high covering the monument. There are no bearing trees available in the vicinity of this corner.

UNION COUNTY SURVEYOR
Date Received 9-22-87
Date Filed 9-25-87
By G. LANGLITZ, DEPUTY
File No. 113-87 R

REGISTERED PROFESSIONAL LAND SURVEYOR
James H. Hambleton
9-25-87
OREGON
JULY 10, 1864
JAMES H. HAMBLETON
645

REFER TO SURVEY 28-87

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL) (DEPUTY)