
### CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally under GLO Contract No. 102, executed by Timothy W. Davenport, dated July 20, 1863. Surveyor General field notes state: Set qr. sec. post, made mound of earth and drove charred stake as per inst.



#### DESCRIPTION OF CORNER EVIDENCE FOUND:

Found a 6 ft. diam. pile of stone on West edge of 8 ft. diam. mound of dirt in an area devoid of most stone. Due to the harmony w/ fences to the North, I accept this as being a perpetuation of the original corner.

SEE SURVEY 046-2021

# DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At center of found mound of dirt I set a 2 1/2" x 30" aluminum pipe, 28" in the ground, with 3" aluminum cap marked as shown below and in a 4 ft. diam. mound of stone, from which:

#### NEW BEARING OBJECTS:

A 5/8" x 30" iron pin bears North  $44^{\circ}43$ ' East, a dist. of 18.50 ft., with 1 1/2" aluminum cap marked NE RP.

A 5/8" x 30" iron pin bears South 21°40' East, a dist. of 18.68 ft., with 1 1/2" aluminum cap marked SE RP.

A  $5/8" \times 30"$  iron pin bears South 45°17' West, a dist. of 23.59 ft., with 1 1/2" aluminum cap marked SW RP.

A 5/8" x 30" iron pin bears North 40°43' West, a dist. of 20.95 ft., with 1 1/2" aluminum cap marked NW RP.

Set steel fence post approx. 1 ft. North

I hereby certify that the corner was monumented on September 29, 2021.

Witness: Kyle A. Tucker,

PROFESSIONAL LAND SURVEYOR

JEFFREY S. HSU 83571

OREGON

Renewal Date: June 30, 2023

UNION COUNTY
SURVEYOR

Date Received 11 1 2 1

Date Filed 11 1 7 1

File Number 059-7001R

I used a Leica GS 18 to determine the distances and bearings of the bearing objects. Measurements are made to the center of the aluminum caps. Basis of Bearing is as per Survey 046-2021.