


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This $\frac{1}{4}$ corner was set by deputy surveyor D. P. Thompson, under Contract No. 103, dated Sept. 3, 1863. He states he set a post for the $\frac{1}{4}$ corner in a mound of earth with charred stake, pits and trenches as per instruction.



Description of corner evidence found:

At the assumed $\frac{1}{4}$ corner location which falls on a very rocky slope I found an unmarked stone 15" x 13" x 6" setting upright in a small mound of stone. No evidence of a mound of earth as time has weathered and washed away any loose soil. No other evidence available.

Description of monument and accessories I established to perpetuate the original location of this corner:

With no other evidence available and the corner position appears correct by survey, I accepted the stone and mound as being the true corner location. I then set an Alum. cap on a 2" x 30" pipe, with a magnet fixed in the cap, at the corner location. I buried the pipe to within 18" above the surface of the ground. I then placed a mound of stone 4 feet dia. and 2 feet high about the pipe and covering the monument. I buried the 15" x 13" x 6" stone along the west side of the monument. No bearing trees are available in the vicinity of this corner.

**UNION COUNTY
SURVEYOR**

Date Received 9-22-87

Date Filed 9-25-87

By G. LANGLITZ, DEPUTY

File No. 132-87 R

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James H. Hambleton
9-25-87

OREGON
JULY 10, 1964
JAMES H. HAMBLETON
645

REFER TO SURVEY 28-87

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL) (DEPUTY)