


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:



This $\frac{1}{4}$ corner was set by deputy surveyor D. P. Thompson, under Contract No. 103, dated Sept. 3, 1863. He states he set a post for $\frac{1}{4}$ corner in a mound of earth with a charred stake, pits & trenches as per instruction.

Description of corner evidence found:

At the assumed $\frac{1}{4}$ corner location I found no trace of the original corner as the area around the corner was a field that had been plowed for many years, but now has been turned back to range land.

Description of monument and accessories I established to perpetuate the original location of this corner:

With no available evidence of the original corner and the main thread of a nearby spring branch, mentioned in the GLO notes, appeared to have been altered, I determined it necessary to use single proportioning to establish this $\frac{1}{4}$ corner. I then set an Alum. cap on a 2" x 30" pipe, with a magnet fixed in the cap, at the corner location. I buried the pipe flush with the surface of the ground. I then placed a mound of stone $3\frac{1}{2}$ feet dia. and 12" high about the pipe and covering the monument. There are no bearing trees in the vicinity of this corner.

UNION COUNTY SURVEYOR
Date Received <u>9-22-87</u>
Date Filed <u>9-25-87</u>
By <u>G. LANGUITZ, DEPUTY</u>
File No. <u>130-87R</u>

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>James H. Hambleton</i>
<u>9-25-87</u>
OREGON JULY 10, 1954 JAMES H. HAMBLETON 645

REFER TO SURVEY 28-87

Office of..... County of.....
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL) (DEPUTY)