CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This section corner was set by deputy surveyor Timothy W. Davenport, under Contract No. 102, dated July 20, 1863. He states he set a post for corner to Sec's 24, 25, and 19, 30. Made mound of earth and drove charred stake as per instruction.

T 5 S R 38 E R 39 E S 24 | S 19 S 25 | S 30 1987 ORLS 645

Description of corner evidence found:

At the assumed section corner location I found no trace of the original corner. Spring branch that is South 3.40 chains has no definite thread; it spread out too much so could not use this GLO call to restore this corner.

Description of monument and accessories I established to perpetuate the original location of this corner:

With no acceptable evidence of the original corner I then established the section corner by single proportioning. I then set an Alum. cap on a 2" x 30" pipe, with a magnet fixed in the cap, at the corner location. I buried the pipe flush with the surface of the ground. I then placed a small mound of stone $2\frac{1}{2}$ feet dia. 6" high covering the monument, from which I set two bearing trees:

A pine 23" dia. bears S 07 45 W, 123.38 feet and scribed T 5 S R 38 E S 25 BT. A pine 23" dia. bears S 39 17 E, 83.23 feet and scribed T 5 S R 39 E S 30 BT.

No other trees are available.

	UNION COUNTY SURVEYOR	REGISTERED PROFESSIONAL
	Date Received 9-22-87	LAND SURVEYOR
	Date Filed 9-25-87	9-25-87
	BY G. LANGLITZ DEPUT	OREGON JULY 10, 1984 JAMES H. HAMBLETON
	Flo No. 134-87 R	645
	REFOR TO SURVEY 28-	87
Office of	County of	•••••
	ertify that the within instrument was filed	
or record on the day of		
(COUNTY OFFICIAL)	by	