


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**History of original corner establishment:**

This  $\frac{1}{4}$  corner was set by deputy surveyor D. P. Thompson, under Contract No. 103, dated Sept. 3 1863. He states he set a post for the  $\frac{1}{4}$  sec. corner in a mound of stone.



**Description of corner evidence found:**

At the assumed  $\frac{1}{4}$  corner location I found a mound of stone with a soft center, as if maybe a post had been placed there, and has since rotted away. No other evidence was available.

**Description of monument and accessories I established to perpetuate the original location of this corner:**

With no other evidence available and the corner position appears correct by survey, I accepted the center of the mound of stone as the true  $\frac{1}{4}$  corner. I then set an Alum. cap on a 2" x 30" pipe, with a magnet fixed in the cap, at the corner location. I buried the pipe to within 12" above the surface of the ground. I then placed a mound of stone 4 feet dia. and  $1\frac{1}{2}$  feet high covering the monument. There are no bearing trees in the vicinity of this corner.

<b>UNION COUNTY SURVEYOR</b>	
Date Received	<u>9-22-87</u>
Date Filed	<u>9-25-87</u>
By	<u>G. LANGLITZ, DEPUTY</u>
File No.	<u>128-87 R</u>

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>James H. Hambleton</i>
<u>9-25-87</u>
OREGON JULY 10, 1964 JAMES H. HAMBLETON 645

REFER TO SURVEY 28-87

Office of..... County of.....  
 State of....., I hereby certify that the within instrument was filed in this office  
 for record on the..... day of....., 19.....  
 ..... by .....  
 (COUNTY OFFICIAL) (DEPUTY)

70  
W