### CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## History of original corner establishment:

This  $\frac{1}{4}$  corner was set by deputy surveyor Timothy W. Davenport, under Contract No. 102, dated July 20, 1863. He states he set a quarter sec. post in a mound of earth and drove charred stake as per instructions.

# DIAGRAM T 5 S R 38 E R 39 E \$ 25 | S 30 1987 ORLS 645

### Description of corner evidence found:

At the assumed  $\frac{1}{4}$  corner location I found a mound of earth grown over with heavy sod and grass; the mound agreed as to a distance of 7.25 chains North to a spring branch as was mentioned in the GLO notes.

### Description of monument and accessories I established to perpetuate the original location of this corner:

With the mound of earth agreeing to the GLO calls and appears correct by survey, I accepted the mound as the true  $\frac{1}{4}$  corner. I then set an Alum. cap on a 2" x 30" pipe, with a magnet fixed in the cap, at the corner location. I buried the pipe to within 6" above the ground. I then placed a mound of stone 3 feet dia. and 1 foot high covering the monument. There are no bearing trees available in the vicinity of this corner.

	UNION COUNTY SURVEYOR	REGISTERED
	Date Received 9-22-87	PROFESSIONAL LAND SURVEYOR
	Date Filed 9-25-87	9-25-87
	BY G. LANGLITZ DEPUTY	OREGON JULY 10, 1964 JAMES H. HAMBLETON
	File No. 135-87 R	645
R	EFFER TO SURVEY 28-	67
Office of		
State of, / hereby cer	tify that the within instrument wee fi	lad in this setting
for record on the day of		ou in this office
(COUNTY OFFICIAL)	by	······································

(DEPUTY)

Form R6-7100-57 (9/71)

(COUNTY OFFICIAL)

₩ GPO--798-276