


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

The South $\frac{1}{4}$ of Sec. 34 T 5 S R 39 E set by deputy Surveyor Timothy W. Davenport, under Contract No 102, dated July 20, 1863. He states he set a quarter section post and made a mound of rock.



Description of corner evidence found:

At the assumed corner location I found a mound of rock as described by Mr. Davenport. No other evidence was available, however the position appears correct both by line and being within 9,58 feet of exactly 3.5 miles. Therefore, I accepted its position as being the true $\frac{1}{4}$ corner.

Description of monument and accessories I established to perpetuate the original location of this corner:

No monument was set during this survey. I left the mound of stone in the same condition as I found it.

UNION COUNTY SURVEYOR
Date Received <u>9-22-87</u>
Date Filed <u>11-2-87</u>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>152-87 R</u>

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>James H. Hambleton</i>
9-25-87
OREGON JULY 10, 1864 JAMES H. HAMBLETON 645

REFER TO SURVEY ~~152~~ 28-87

Office of..... County of.....
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL) (DEPUTY)