


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 5 S R 40 E G-22



DESCRIPTION OF CORNER EVIDENCE FOUND:

None found.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by Survey I set a 5/8" x 30" iron pin, 28" in the ground, with 2 1/2" aluminum cap marked as shown below, with 2' diam. collar of stone, from which:

NEW BEARING OBJECTS:

A 13" Ponderosa Pine bears North, a dist. of 8.25 ft, marked CW 1/16 S12 BT

A 7" Douglas Fir bears South 45° East, a dist. of 36.50 ft, marked CW 1/16 S12 BT

Set steel fence post approx. 1 ft. South


I hereby certify that the corner was monumented on October 22, 2021.

Witnesses: Kyle Tucker, Emmitt Ambert

<p>REGISTERED PROFESSIONAL LAND SURVEYOR</p> 
<p>OREGON June 2, 2010 JEFFREY S. HSU 83571</p>

Renewal Date: June 30, 2023

<p>UNION COUNTY SURVEYOR</p>
Date Received <u>11/1/21</u>
Date Filed <u>11/1/21</u>
Filed By <u>Neil Gilliam DEPUTY</u>
File Number <u>042-2021R</u>



I used a steel tape and magnetic compass in establishment of the new accessories. I use 14° East magnetic declination. Distances are to a 60d spike riven into the right side of the roote crown onf the bearing trees. Bearings are to a brass washer marked OPLS 83571 in the BT blaze of the new bearing tees.