
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original corner establishment:

Corner not established in original survey



No record of subsequent remonumentation found in county records Description of corner evidence found:

NONE



See map of survey dated June, 1986

REGISTERED PROFESSIONAL AND SURVEYOR

> ORESON ALY 10, 1964

DUANE I. GRIFFITH


Description of monument and accessories lestablished to perpetuate the original location of this corner: At position determined by survey, I set a 2½1×3011 aluminum pipe with aluminum cap marked as shown, 28 inches in the ground from which:

New BTs

A 13 inch diameter P.Pine bears N10°E 18.19 feet marked CN 1/16 S24 BT A 13 inch diameter P.Pine bears N88°W 33.24 feet marked X BT

Set steel fenceposts approximately 5 feet West with 54-2 sign and approximately 5 feet North with 54-2 and 54-9 signs attached

Corner set May 30, 1986 Witness: Greg Blackman



Brass washer marked OPLS 644 nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of	County of
	ify that the within instrument was filed in this office
for record on the day of	
••••••	. by
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

☆U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276