
CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original corner establishment:

Corner not established in original survey



No evidence found of subsequent remonumentation in the county records Description of corner evidence found:

NONE



See map of survey dated June, 1986


Description of monument and accessories lestablished to perpetuate the original location of this corner: At position determined by survey, I set a 2½1×3011 aluminum pipe with aluminum cap marked as shown, 27 inches in the ground with mound of stone 3 ft. base to top of cap from which:

New BTs

A 13 inch diameter P.Pine bears N54°E 54.91 feet marked SW 1/16 S24 BT A 13 inch diameter Red Fir bears S87°E 19.74 feet marked SW 1/16 S24 BT

Set steel fenceposts approximately 5 feet East with 54-2 sign and approximately 5 feet North with 54-2 and 54-9 signs attached

Corner set May 27, 1986 Witness; Rick Robinson



PROFESSIONAL LAND SURVEYOR

OREGON
ALY 10, 1804

DUANE 1. GRIFFITH

REGISTERED

644

Brass washer marked OPLS 644 nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of	
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

☆U.S. GOVERNMENT PRINTING OFFICE -1983-793-276