


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not established in original survey



No record of subsequent remonumentation found in county record

Description of corner evidence found:

NONE

**UNION COUNTY SURVEYOR**

---

Date Received 6-5-86

Date Filed 6-18-86

By G. LANGRITZ, DEPUTY

File No. 62-86 R

See map of survey dated June, 1986

Description of monument and accessories established to perpetuate the

original location of this corner: At position determined by survey, I set a 2 1/2" x 30" aluminum pipe with aluminum cap marked as shown, 30 inches in the ground with small mound of stone from which;


New BTs;

A 28 inch diameter double bole Red Fir bears N67°E 28.57 feet marked CS 1/16 S24 BT  
A 13 inch diameter P.Pine bears S31°E 26.39 feet marked CS 1/16 S24 BT

Set steel fenceposts approximately 5 feet West with 54-2 sign and approximately 5 feet East with 54-2 and 54-9 signs attached

Corner monumented May 27, 1986

Witness: Rick Robinson



Brass washer marked OPLS 644 nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d spike set in right side of tree when facing tree, unless otherwise stated.

**REGISTERED PROFESSIONAL LAND SURVEYOR**

*Handwritten signature of Duane I. Griffith*

OREGON  
JULY 10, 1984  
**DUANE I. GRIFFITH**  
644

Office of..... County of.....  
State of....., I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)