
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not established in original survey



No record of subsequent remonumentation found in county records

Description of corner evidence found:

NONE



Date Received 6-5-86

Date Filed 6-18-86

LANGLIZ DOPU

File No 59 - 86 D

See map of survey dated June, 1986

Description of monument and accessories I established to perpetuate the


original location of this corner: At position determined by survey, I set a 2½ ×30" aluminum pipe with aluminum cap marked as shown, 26 inches in the ground with a small mound of stone from which:

New BTs

A 8 inch diameter White Fir bears S60°E 24.93 feet marked E1/16 S25 BT A 13 inch diameter Tamarack bears N12°W 14.44 feet marked E1/16 S24 BT

Set a steel fencepost approximately 5 feet East with 54-2 sign and approximately 5 feet North with 54-2 and 54-9 sign attached

Corner set May 30, 1986 Witness: Greg Blackman



PROFESSIONAL
LAND SURVEYOR

OREGON
ANY 10, 1864

DUANE I. GRIFFITH
644

REGISTERED

Brass washer marked OPLS 644 nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of	R
for record on the day of	

Form R6-7100-57 (9/71)

☆U.S. GOVERNMENT PRINTING OFFICE -1983-793-276