CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX NO. 0.5-19.

History of original corner establishment:

DIAGRAM T5S R41E

C-S-N 1/64

S23

None. Corner established this survey.

1994

Description of Corner Evidence Found:

CORNER TREE

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner position falls in the center of a 14" dia., Western Larch Tree. Scribed on the North side of tree: "CSN 1/64 S23 COR": with bottom of blaze 3 ft. above root crown. Placed 1/2" brass disc stamped: "L. MILLER PLS 2513" at bottom of blaze. On South side of tree placed an 8" spike just above root crown. Placed Land Survey Monument (54-9) signs on both north and south sides of corner trees and painted 6" red band above signs.

From Which:

A 5/8" x 30" rebar, 24" into ground with a 2" aluminum cap marked: L. MILLER RM 1994 PLS 2513. Bears S88°47'15"W, 50.24 ft. dist.

A 5/8" x 30" rebar, 24" into ground with a 2" aluminum cap marked: L. MILLER RM 1994 PLS 2513. Bears S01°05'29"W, 50.00 ft. dist.

Measurements to RM taken with Total Station and based on control network.

This monumentation was performed by: Linda Lee Miller, PLS 2513 Witnessed by: Russell Avery, PE, PLS August 24, 1994

