
# CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original corner establishment:

Corner not set on original survey.



Description of corner evidence found:

NONE



See map of survey number 31-86 filed in the office of the Union County Surveyor Description of monument and accessories I established to perpetuate the


original location of this corner: At position determined by survey, I set a  $2\frac{1}{2}x30$  aluminum pipe with aluminum cap marked as shown 29 inches in the ground, from which:

A 19 inch Ponderosa Pine bears N 31° E, 265.84 feet, marked W 1/16 S31 BT.

A 16 inch Ponderosa Pine bears S 39° E, 205.62 feet, marked W 1/16 S 6 BT.

Set a steel fence post approximately 5 feet West with a 54-9 sign attached.

Corner set: 9/17/86
Witness: Greg Blackman, Rick Robinson



Brass washer marked OPLS 644 nailed to BT Blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d Spikeset in right side of tree when facing tree, unless otherwise stated.

PROFESSIONAL LAND SURVEYOR	
Vem I thuff	_
OREGON JULY 10, 1964  DUANE I. GRIFFITH 644	

Office of	County of
State of, / he	ereby certify that the within instrument was filed in this office
for record on the day of	
	by
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

\$U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276

# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

### HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by Union County Survey Number 31-86 by Duane I. Griffith, OPLS 644. Monumentation record 258-86R states:

At position determined by survey, I set a 24'x30" aluminum pipe with aluminum cap marked as shown 29" in the ground from which:
A 19" Ponderosa Pine bears N31°E, 265.84 feet, marked W 1/16 S31 BT
A 16" Ponderosa Pine bears S39°E, 205.62 feet, marked W 1/16th S6 BT

No record of subsequent monumentation found in UNION COUNTY survey records.

# T 5 S R 41 E A-02

### DESCRIPTION OF CORNER EVIDENCE FOUND:

Found Aluminum monument as described above and shown below. Found NE bearing tree live and vigorous at record position. Found SE bearing tree at record position, but tree is now a snag.

See Survey Number 031-2000.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

## NEW BEARING TREE:

A 18 inch diameter Ponderosa pine bears South 62° East, 228.54 feet marked W 1/16 S6 BT

Set steel fence post 2 feet North of monument.

I hereby certify that the corner was perpetuated on October 3, 2000. Witnesses: Norbert Volny and Greg Blackman Jr.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
July 17 1980

RICK G. ROBINSON
2219

Berrewel Date December 31, 2000

S 6 T 5 S 1986 OPLS 644

UNION COUNTY
SURVEYOR

Data Received 10/10/2000

Data Filed 10/3/100

Filed By 10/2000

Filed By 10/20

I used a total station instrument in the establishment of the new accessories. I used the same solar observation as survey number 031-2000 as the basis of bearing. I attached a brass washer marked OPLS 2219 to the BT blaze. The distance to the new bearing tree is to a 50d spike driven on the right side of the tree at the root crown.

# <u>CATIFIED RECORD OF LAND CORNER MONUMENTATION</u>


# HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by Union County Survey Number 31-86 by Duane Griffith. Monumentation record 258-86R states:

At position determined by survey, I set a 2 1/2"x30" aluminum pipe with aluminum cap marked as shown, 29" in the ground from which:

- A 19" ponderosa pine bears N31°E, 265.84 feet, marked W 1/16 S31 BT.
- A 16" ponderosa pine bears S39°E, 205.62 feet, marked W 1/16 S6 BT.

Corner recovered in Union County Survey Number 031-2000, by Rick Robinson. The monument and Northeast bearing tree are found in position, but the Southeast bearing tree is a snag. Monumentation record 024-2000R states:



#### NEW BEARING TREE:

A 18 inch diameter Ponderosa Pine bears South 62° East, 228.54 feet, marked W 1/16 S6 BT.

#### DESCRIPTION OF CORNER EVIDENCE FOUND:

Found 2 ½" Aluminum pipe with cap marked as shown below, flush with the ground. Bearing trees are all in place as described on monumentation record 024-2000R, however a forester in the employ of the landowner has informed us that the bearing trees will be logged.

## DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

## TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

From the position of the aluminum pipe monument:

#### NEW BEARING TREES:

An 11 in. diam. Ponderosa Pine bears North  $49^{\circ}03$ ' East, a distance of 211.55 feet, marked W 1/16 S31 BT.

An 8 in. diam. Ponderosa Pine bears South  $46^{\circ}23$ ' East, a distance of 208.45 feet, marked W 1/16 S6 BT.

Corner falls in an open meadow, on the West side of a North/South running fenceline.

I hereby certify that the corner was perpetuated on April 3, 2012.

Witness: Jeff Hsu

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREĞON July 17, 1986

RICK G. ROBINSON 2219

Renewal Date: December 31, 2012

UNION COUNTY
SURVEYOR

Date Received 4/11/12

Date Filed 5/8/17

Filed By 7. Daylor

File Number 02/2012/2

I used a Leica 1200 RTK GPS in the establishment of the accessories. Basis of bearings as as per Survey Number 025-2010. The distances are to a 60d spike driven into the root crown at the right side of the bearing trees. Bearings of to a brass washer marked OPLS 2219 in the center of the lower BT blaze.