

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 5 S., R. 41 E., Willamette Meridian, Oregon

<p>CHAINS</p> <p>38.385</p>	<p>From this point, the corner of wire fences, extending E. and N., bears S. 25° E., 0.230 chs. dist.</p> <hr/> <p style="text-align: center;">Subdivision of Section 3, T. 5 S., R. 41 E., Willamette Meridian, Oregon</p> <hr/> <p>From the ¼ sec. cor. of secs. 3 and 10. N. 2° 03' 30" W., on the N. and S. center line of sec. 3. Along broken W. slope through logged area.</p> <p>Point for the center ¼ sec. cor. of sec. 3, at intersection with the E. and W. center line.</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.</p>
<p>UNION COUNTY SURVEYOR</p> <p>Date Received <u>3/5/13</u></p> <p>Date Filed <u>3/5/13</u></p> <p>By <u>[Signature]</u></p> <p>File No. <u>026-203R</u></p>	<p style="text-align: center;">T 5 S R 41 E C ¼ S 3 1991</p> <p>from which</p> <p>A lodgepole pine, 9 ins. diam., bears N. 89° E., 32½ lks. dist., mkd. C ¼ S3 BT.</p> <p>A larch, 16 ins. diam., bears S. 54° W., 65 lks. dist., mkd. C ¼ S3 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the iron post.</p>
<p>39.40</p>	<p>Descend steep N. slope to Little Catherine Creek; thence across creek and asc. S. slope.</p>
<p>56.375</p>	<p>Point for the center N 1/16 sec. cor. of sec. 3.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, and in a collar of stone, with brass cap mkd.</p> <p style="text-align: center;">N 1/16 S 3 C 1991</p> <p>from which</p> <p>A fir, 28 ins. diam., bears N. 48° E., 25 lks. dist., mkd. CN 1/16 S3 BT.</p> <p>A ponderosa pine, 33 ins. diam., bears S. 78° W., 77 lks. dist., mkd. CN 1/16 S3 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p> <p>Ascend SW. slope, through medium timber and light undergrowth.</p>