

485

Subdivision of Section 3,
T. 5 S., R. 41 E., Willamette Meridian, Oregon

CHAINS	
31.60	Spur, slopes N.
39.00	Spur, slopes N.; desc. NW. slope.
41.215	The N 1/16 sec. cor. of secs. 3 and 4.
<hr/> <p>Subdivision of Section 4, T. 5 S., R. 41 E., Willamette Meridian, Oregon</p> <hr/>	
	From the 1/4 sec. cor. of secs. 4 and 9.
	N. 1° 40' 30" W., on the N. and S. center line of sec. 4.
	Descend broken N. slope, through medium timber and undergrowth.
33.75	Stream, 30 lks. wide, course irregularly S.
34.40	Dirt road, 20 lks. wide, bears N. and S. 30° W.
38.380	Point for the C 1/4 sec. cor. of sec. 4, at intersection with the E. and W. center line.
	Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, and in a collar of stone, with brass cap mkd.
	<p>T 5 S R 41 E C 1/4 S 4 1991</p>
	from which
	A spruce, 22 ins. diam., bears N. 53° E., 57 lks. dist., mkd. C 1/4 S4 BT.
	A larch, 15 ins. diam., bears S. 55° W., 16 lks. dist., mkd. C 1/4 S4 BT.
	Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.
	The corner is located in the cutbank of an unimproved road, bearing N. and S.
	Ascend over SE. slope.
74.740	The 1/4 sec. cor. of secs. 4 and 33 on the N. bdy. of the Tp., reestablished by proportionate measurement and recorded by Duane I. Griffith, Registered Land Surveyor No. 644, in 1986, recorded under file No. 123-86R; there is no remaining evidence of the original corner, therefore, this position is accepted as the corner, monumented with an aluminum pipe, 2 1/2 ins. diam., firmly set flush with the ground, and in a mound of stone, 3 ft. base, with aluminum cap mkd.

UNION COUNTY SURVEYOR	
Date Received	3/5/13
Date Filed	3/5/13
By	<i>[Signature]</i>
File No.	028-2013R