CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1879, Henry M. Thatcher, under contract 320, "Set stone 13X9X5 for 1/4 sec. cor. From which A Pine 5 in. in dia. bears N80°E, 10lks. dist. A Fir 10 in. in dia. bears S45°W, 36 lks. dist.

In 1990, Philip G. Griffin, BLM, under Group No. 1000 & 1484 states: "Point for the 1/4 sec. cor. of secs. 3 and 10 at proportionate distance there is no remaining evidence of the original corner. Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with From which:

File Index E - 15DIAGRAM R 41 E S 3 S 10

brass cap mkd. T 5 S R 41 E S 3 1/4-10 S 1990

A larch, 18 ins. diam., bears N. 79° E., 36 lks. dist., mkd. 1/4 S3 BT. A larch, 9 ins. diam., bears S. 74° W., 33 lks. dist., mkd. 1/4 S10 BT."

Description of corner evidence found:

Found:

A stainless steel post, 6 ins. above ground, 2 1/2 ins. diam., with BLM brass cap mkd. From which

A larch, 18 ins. diam., bears N. 79° E., 23.8 ft. dist., mkd. 1/4 S3 BT. A larch, 9 ins. diam., bears S. 74° W., 21.8 ft. dist., mkd. 1/4 S10 BT.

T 5 SR 41 E S 3 1/4-S 10 1990

Description of monument and accessories I established to perpetuate the original location of this corner:

From the 1990 BLM monument new bearing trees

A larch, 15 ins. diam., bears N. 13° E., 38.4 ft. dist., mkd. 1/4 S3 BT. A larch, 14 ins. diam., bears S. 16 1/2° W., 85.7 ft. dist., mkd. 1/4 S10 BT.

The trees are double blazed, with a brass washer, mkd. LS 2211, nailed between the B & T.

Tools used; hand compass (declination 19.5° East) and a 200 ft. Kesson tape.

Crew members: Earl E. Strang & Roger O. Green

I hereby certify the above corner point was perpetuated as hereon described, on June 9, 1993.

REGISTERED **PROFESSIONAL** LAND SURVEYOR OREGON JULY 17, 1986 ROGER O. GREEN

Roger O. Green, LS 2211, Forest Service Land Surveyor 3502 Highway 30, La Grande, Oregon, 97850

SEALED: JULY 30, 1993

State of, I hereby certify that the within	instrument was filed in this off
for record on the day of, 19	Carrie Carr
(COUNTY OFFICIAL)	(DEPUTY)
orm R6-7100-57 (9/71)	. Data Riccived 11/19/83
	tuto Filed 12/14/83
	By Strong T-Olas
	No 058-1993 R

*GPO-591-971, 1988



File No. 041-2013R

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 5 S., R. 41 E., Willamette Meridian, Oregon

CHAINE		
CHAINS		
	E 1/16 ——	
_	S 10 1990	
	from which	
	A lodgepole pine, 10 ins. diam., bears N. 26° E., 18 lks. dist., mkd. E 1/16 S3 BT.	*
	A larch, 16 ins. diam., bears S. 42° W., 84 lks. dist., mkd. E 1/16 S10 BT.	
	Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.	
21.15	Graveled road, 20 lks. wide, bears N. 80° E. and S. 60° W., in a curve.	
32.75	Same graveled road, 20 lks. wide, bears N. 30° W. and S. 30° E.; desc. broken W. slope through logged area.	p
39.760	Point for the $\frac{1}{4}$ sec. cor. of secs. 3 and 10 at proportionate distance; there is no remaining evidence of the original corner.	
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.	
	T 5 S R 41 E	
	S 3	
	s 10 1990	
	from which	
	A larch, 18 ins. diam., bears N. 79° E., 36 lks. dist., mkd. ¼ S3 BT. A larch, 9 ins. diam., bears S. 74° W., 33 lks. dist., mkd. ¼ S10 BT.	
-	Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.	
	Descend NW. slope changing to W. slope and SW. slope, through logged area.	
79.520	The cor. of secs. 3, 4, 9, and 10.	
	N. 3° 34' 00" W., bet. secs. 3 and 4.	
	Descend gradual NW. slope. UNION COUI	AIA
1.50	Graveled road, 25 lks. wide, bears N. 30° E. and S. 50° W. in a curve; continue along broken W. slope through medium timber and undergrowth. Date Received	15/13
	7/-/	
	Date Filed 3/5/	13 n
	By ALSAL	w -
		Control of the Contro