

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 5 S., R. 41 E., Willamette Meridian, Oregon

CHAINS 17.00 19.965	<p>Along ridgetop through medium timber and undergrowth.</p> <p>Descend NE. slope.</p> <p>Point for the N 1/16 sec. cor. of secs. 10 and 11.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, and in a collar of stone, with brass cap mkd.</p> <div style="text-align: center;"> <table border="0"> <tr><td colspan="2">N 1/16</td></tr> <tr><td>S 10</td><td>S 11</td></tr> <tr><td colspan="2">1990</td></tr> </table> </div> <p>from which</p> <p>A spruce, 19 ins. diam., bears N. 80° E., 14 lks. dist., mkd. N 1/16 S11 BT.</p> <p>A larch, 13 ins. diam., bears N. 15° W., 99 lks. dist., mkd. N 1/16 S10 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p> <p>Continue to descend NE. slope changing to SW. slope and W. slope.</p>	N 1/16		S 10	S 11	1990											
N 1/16																	
S 10	S 11																
1990																	
39.930	<p>Point for the cor. of secs. 2, 3, 10, and 11 at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, and in a collar of stone, with brass cap mkd.</p> <div style="text-align: center;"> <table border="0"> <tr><td colspan="2">T 5 S</td><td colspan="2">R 41 E</td></tr> <tr><td>S 3</td><td>S 2</td><td colspan="2"></td></tr> <tr><td>S 10</td><td>S 11</td><td colspan="2"></td></tr> <tr><td colspan="4">1990</td></tr> </table> </div> <p>from which</p> <p>A larch, 15 ins. diam., bears N. 7½° E., 121 lks. dist., mkd. T5S R41E S2 BT.</p> <p>A lodgepole pine, 15 ins. diam., bears S. 70° E., 69 lks. dist., mkd. T5S R41E S11 BT.</p> <p>The marks BXO on the N. end of a rock outcrop, 8½ ft. long, 2½ ft. wide, 5 ft. high, bear S. 9° W., 33 lks. dist.</p> <p>A lodgepole pine, 12 ins. diam., bears N. 30° W., 43 lks. dist., mkd. T5S R41E S3 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p> <p>The corner is located on a ridgetop, bearing N. and S.</p>	T 5 S		R 41 E		S 3	S 2			S 10	S 11			1990			
T 5 S		R 41 E															
S 3	S 2																
S 10	S 11																
1990																	

UNION COUNTY SURVEYOR	
Date Received	3/5/13
Date Filed	3/5/13
By	<i>[Signature]</i>
File No.	043-2013R