NPW . srm 76 Jun 1949	CADASTRAL RETHACEMENT RECORD	
Corner North 1/16 corner		
From original G. L. O. field notes,	datedEVIDENCE FOLIND:	T
Corner		
Witness		-
Marks		
From re-establishment field notes, dated	dated CACRED PROFESS EVIDENCE FOUND: SURVEYOR 19	
	年 3780 元 Date Received	-
Witness	(50)	1 1
	LAM W. BRIGG	
	File No. 718-84R	1
•	RETRACEMENT NOTES: Set brass cap in concrete. Set steel fence post along side corner. Blazed and scribed bearing trees:	1
	W, 2	, ,
	MALES CORTS IN (12)	
	Oregon License No. 3780 Milliam 1119. Areasis	. F
	June 10, 1975 William W. Briggs, P.E Senior Vice Presiden	5
	J-U-B ENGINEERS, Inc.	

T5SR41E

SET BY WWB RPE NO 3780

Diagram

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

North 1/16 Section Corner of Sections 7 & 8, T.5S., R.41E., W.M.

History of original corner establishment:

1975, William W. Briggs, P.E. No. 3780, J-U-B Engineers, Inc., conducted a dependent resurvey of Sec. 7, county survey record No. 16-75, 17-75, & remonumentation record No. 718-84R, his record states:

"Set brass cap in concrete. Set steel fence post along side corner. Blazed and scribed bearing trees:

> 12" Ponderosa Pine, bears N12°W, 23.10 feet 11" Ponderosa Pine, bears N77°E, 38.10 feet"

1977, Duane I. Griffith, L.S. No. 644, Bagett, Griffith & Associates, conducted a retracement of a portion of Sec. 7 & a partial sec. subdivision, county survey No. 7-77, which states:

"Found Monument of Record"

1991, Philip G. Griffin, Cadastral Surveyor, BLM, conducted a dependent resurvey in this township and accepted this corner as established and recorded by Briggs, his record states:

"...monumented with a brass cap, 3 ins. diam., firmly set in concrete flush with the ground, with top mkd." (as shown in the diagram above).

"from which bearing trees mkd. by Briggs

A ponderosa pine, 14 ins. diam., bears N. 77 3/4° E., 57 1/2 lks. dist., with fragmentary scribe marks on partially healed blaze.

A ponderosa pine, 15 ins. diam., bears N. 12 3/4° W., 35 lks. dist., with fragmentary scribe marks on partially healed blaze."

Description of corner evidence found:

Found corner monumented with a brass cap, 3 ins. diam., firmly set in concrete flush with the ground. with top mkd. as shown in the diagram above,

from which bearing trees mkd. by Briggs

A ponderosa pine, 15 ins. diam., bears N. 77 3/4° E., 38.0 ft. dist., with fragmentary scribe marks on partially healed blaze.

A ponderosa pine, 16 ins. diam., bears N. 12 3/4° W., 23.1 ft. dist., with scribe marks "S7 BT" visible on partially healed blaze.

Description of monument and accessories I established to perpetuate the original location of this corner:

From the brass cap, I established the following references:

I set a galvanized steel post, Northerly on the property line, 4.6 ft. dist., with a Property Boundary sign attached, I also set a galvanized steel post, Southerly on the property line, 2.0 ft. dist., with a Property Boundary sign attached.

UNION COUNTY **SURVEYOR** Date Received

Barbed wire fence just East of the corner extends north & south. This corner is visible from a dirt road, about 300 feet to the east.

I hereby certify that the above corner was perpe me and my crew on June 9, 1998.

Compass declination used 18 1/2° East.

See also, filed survey plat.

Witnessed by crew member: Roanna K. Tomlinson

JUL 20 1998.

Current registration

period ends 6-30-99

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 5 S., R. 41 E., Willamette Meridian, Oregon

A 600	eareth	T. 5 S., R. 41 E., Williamette Meridian, Oregon	
	CHAINS 20.685	The N 1/16 sec. cor. of secs. 7 and 8 established and recorded by William W. Briggs, Registered Professional Engineer No. 3780, in 1975, recorded under file No. 718-84R, and is accepted as the corner, monumented with a brass cap, 3 ins. diam., firmly set in concrete flush with the ground, with top mkd.	
		N 1/16 S 7 S 8 1975 SET BY WWB RPE NO 3780	
		from which bearing trees mkd. by Briggs	
		A ponderosa pine, 14 ins. diam., bears N. 77½° E., 57½ lks. dist., with fragmentary scribe marks on partially healed blaze.	
		A ponderosa pine, 15 ins. diam., bears N. 12¾° W., 35 lks. dist., with fragmentary scribe marks on partially healed blaze.	
		N. 0° 56′ 30" E., beginning new measurement.	
		Ascend SW. slope, along barbed wire fence.	
	20.685	The cor. of secs. 5, 6, 7, and 8, perpetuated from the original corner stone, no longer visible, and recorded by William W. Briggs, Registered Professional Engineer No. 3780, in 1975, recorded under file No. 716-84R, monumented with a brass cap, 3 ins. diam., firmly set in concrete flush with the ground, with top mkd.	
		T 5 S R 41 E S 6 S 5 S 7 S 8 1975 SET BY WWB RPE 3780	
		from which bearing trees mkd. by Briggs	
		A ponderosa pine, 10 ins. diam., bears N. 68½° E., 36 lks. dist., with fragmentary scribe marks on partially healed blaze.	
	COUNTY EYOR	A ponderosa pine, 14 ins. diam., bears S. 36° E., 76 lks. dist., with fragmentary scribe marks on partially healed blaze.	
Date Received_	3/5/13	A ponderosa pine, 14 ins. diam., bears S. 40½° W., 43 lks. dist., with pitched over blaze.	
Date Filed	3/5/13	A ponderosa pine, 13 ins. diam., bears N. 17½° W., 17 lks. dist., with pitched over blaze.	
Dy 1146	16m 45-7013R	The corner is located at the SW. edge of a dirt road, 15 lks. wide, extending NW. and SE., and at the cor. of wire fences, extending S. and W.	
Berg Carlown And Recognization and Europe (Publish Section 2 Transport Recognization)	en ett en socialistikkalasistik oliki kunikun että silankin en saat suosiden ellä siit jähdelet konnattaata	S. 89° 22′ 30" W., bet. secs. 6 and 7.	***************************************