
## UNION COUNTY CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

Corner not previously established.

See map of survey number 019-1992

Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey , I set a  $2\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap marked as shown, 16 inches in the ground, from which;

New bearing trees:

A 17 inch diameter Ponderosa Pine bears S57°E, 37.48 feet marked 1/16 S8 BT A 14 inch diameter Ponderosa Pine bears S87°W, 35.80 feet marked 1/16 S7 BT

Set a steel fencepost approximately 2 feet north with a Land Survey Monument sign attached.

I painted red bands around the bearing trees and attached land survey monument and bearing tree signs to the trees.

I raised a mound of stone, 3 foot base to top of cap.

I hereby certify that the above corner point was pestablished as hereon described on June 10, 1992.

Witness: Greg Blackman G.T. Blackman

> REGISTERED TOFESSIONAL OD SURVEYOR

DUANE L GRIFFITH

l used a steel tape and magnetic compass in the establishment of new corner accessories. I used 20° magnetic declination. The distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

R41E 1/16

S 7 | S 8 1992 OPLS 644

Data Raceived 6/17/92

Data Filed 6/20/92

By How Alactic

H-05