


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:
Corner not previously established.

T 5S R 41 E H-09



DESCRIPTION OF CORNER EVIDENCE FOUND:
None.

See Survey Number 054-2013

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 5/8"x30" iron pin, 30 inches in the ground, with 2 1/2" aluminum cap, marked as shown below, from which:

A 15 inch Ponderosa Pine bears North 46° East, a distance of 22.75 feet, marked S 1/16 S9 BT.


A 9 inch Ponderosa Pine bears North 49° West, a distance of 9.00 feet, marked S 1/16 S8 BT.

I set a steel fencepost approximately 1/2 ft. North of the corner. Corner falls 2 feet East of a South running fenceline, approximately 35 feet East and 15 feet North of a fence corner, from which the fences run North and West.

I hereby certify that the corner was monumented on December 9, 2013.



Renewal Date: June 30, 2015



UNION COUNTY SURVEYOR

Date Received 12/10/13

Date Filed 12/10/13

Filed By [Signature]

File Number 448-2013R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination. The distances to the new bearing trees are to a 60d spike driven into the root crown at the right side of the bearing trees. Bearings are to a brass washer marked OPLS 83571 in the BT blaze.