

476

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 5 S., R. 41 E., Willamette Meridian, Oregon

CHAINS

T 5 S R 41 E

S 17 | S 16

S 20 | S 21

1990

from which new bearing trees

A ponderosa pine, 28 ins. diam., bears N. 40° E.,
121 lks. dist., mkd. T5S R41E S16 BT.

A ponderosa pine, 36 ins. diam., bears S. 21° E.,
198 lks. dist., mkd. T5S R41E S21 BT.

A ponderosa pine, 26 ins. diam., bears S. 89½° W.,
369 lks. dist., mkd. T5S R41E S20 BT.

A ponderosa pine, 23 ins. diam., bears N. 75½° W.,
425 lks. dist., mkd. T5S R41E S17 BT.

Deposit a white "DEEP-1" magnetic marker at the base, the iron pipe within, and the corner stone alongside the stainless steel post.

The corner is located 10 lks. S. of a barbed wire fence, extending E. and W.

A thorough search was made for the ¼ sec. cor. of secs. 16 and 17; it was not recovered.

From this same point, the ¼ sec. cor. of secs. 8 and 17, bears N. 89° 48' 30" W., 40.260 chs. dist., monumented with the original slate stone, 16 x 11 x 6 ins. (record, 17 x 13 x 7 ins.), firmly set, projecting 10 ins. above ground, mkd. ¼ on the S. face, from which bearing trees not of record:

A ponderosa pine, 15 ins. diam., bears S. 67° E.,
22 lks. dist., with healed blaze.

A ponderosa pine, 14 ins. diam., bears N. 26° W.,
26 lks. dist., with healed double blaze.

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd.

T 5 S R 41 E

S 8

¼

S 17

1990

from which new bearing trees

A ponderosa pine, 10 ins. diam., bears N. 14° E.,
55 lks. dist., mkd. ¼ S8 BT.

A ponderosa pine, 10 ins. diam., bears S. 55° E.,
12 lks. dist., mkd. ¼ S17 BT.

UNION COUNTY
SURVEYOR

Date Received

3/5/13

Date Filed

3/5/13

By

N. E. Nunn

File No.

064-2013R

477

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 5 S., R. 41 E., Willamette Meridian, Oregon

CHAINS	<p>Deposit a white "DEEP-1" magnetic marker at the base and the corner stone alongside the stainless steel post.</p> <p>From the ¼ sec. cor. of secs. 8 and 17, the corner of wire fences extending W. and S., bears S. 7° W., 0.360 chs. dist.</p> <p>Also, from the ¼ sec. cor. of secs. 8 and 17, an iron pipe, 2 ins. diam., firmly set, projecting 4 ins. above ground, with metal washer mkd. CX-12 1973 at the center of a mound of stone, with a steel reinforcing rod, 5/8 in. diam., alongside, bears S. 0° 28' 30" E., 0.346 chs. dist.</p>
0.25	<p>N. 1° 44' 30" W., bet. secs. 8 and 9.</p> <p>Ascend SW. slope through medium timber and light undergrowth.</p> <p>Barbed wire fence, extends E. and W.</p>
38.95	<p>Graveled road, 20 lks. wide, bears N. 75° E. and S. 75° W.</p>
39.825	<p>The ¼ sec. cor. of secs. 8 and 9, monumented with an iron post, 2½ ins. diam., firmly set, projecting 8 ins. above ground, and in a mound of stone, 2½ ft. base, to top, with brass cap mkd.</p> <p style="text-align: center;">T 5 S R 41 E S 8 S 9 1971</p> <p>from which remains of the original bearing trees</p> <p style="padding-left: 40px;">A root hole, bears N. 45° E., 24 lks. dist., with remains of a pine alongside, with axe marks.</p> <p style="padding-left: 40px;">A small depression in the ground, bears N. 80° W., 20 lks. dist.</p> <p>and bearing trees mkd. by Albright</p> <p style="padding-left: 40px;">A ponderosa pine, 16 ins. diam., bears S. 78° E., 52½ lks. dist., with scribe marks ¼ S9 BT on open blaze. (Record, S. 75° E.)</p> <p style="padding-left: 40px;">A ponderosa pine, 15 ins. diam., bears N. 43½° W., 94½ lks. dist., with fragmentary scribe marks visible on partially healed blaze. (Record, N. 41½° W., 96 lks.)</p> <p>The corner is located 0.080 chs. W. of a barbed wire fence, extending N. and S.</p>
	<p>N. 0° 27' 30" W., beginning new measurement.</p> <p>Ascend S. slope, along wire fence through medium timber and light undergrowth.</p>

UNION COUNTY SURVEYOR	
Date Received	3/5/13
Date Filed	3/5/13
By	<i>[Signature]</i>
File No.	064-2013R